

## Under Review Notification

**Raised By:** Steven Drouin

**Product #:** D130-1023

**Date:** 19.07.30

**Product Name:** OEM SKIDTUBE TRAINING WEARPLATE

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D350-1023-011	IIN-D350-1023 Rev. B	Y	Y	N	Y	N	Y	Y	19-831	CHG 001
D5404-041	D5404 Rev.B	Y	Y	N	Y	N	Y	Y	19-831	Drawing Update
D5404-042	D5404 Rev. B	Y	Y	N	Y	N	Y	Y	19-831	Drawing Update

### Description of Issue:

Current attachment to fwd saddle on outboard side prone to buckling. New design will attach on both sides to prevent this.

SALES : Do not quote, wait for new design

### Distribution:

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider

Supply Chain Director / Senior Buyer

Marketing Eugene